Approved For Release 2001/07/30 : CIA-RDP78B04747A000500010003-0

99715

24 May 65 — STATINTL

Conf w/ [redacted] re 3x-12x enlarger - All Jiffy made contact wise and those items we were to fix except the vacuum pump. [redacted] stated they did not want the vacuum anyway.

Two areas - brand new - they would like to see something done about ① - move exhaust from rear of condenser housing to top - directly over lamp so dirt is not pulled across condenser. ② The mods performed by PD will not allow film (2 pools) to be taken directly from light table + inserted in machine - support brackets for the film spool STATINTL support rods prevent this.

STATINTL Asked [redacted] to fix the exhaust + [redacted] STATINTL [redacted] to look at the bracket design + see if a fix can be made.

STATINTL Also - they can make no use of counter. Told them this was an operational job - to work out their own system that we were told they wanted a 4 position [redacted] counter which they have - now want to make a system to fit. Also - he can't read it w/o his glasses + it's too tight - Tough!

Declass Review by NIMA / DoD
Approved For Release 2001/07/30 : CIA-RDP78B04747A000500010003-0
STATINTL